



## AXIUS SC, AGT SC, SR-H, SHX, AD-H, BC-H

1




ASME / DIN 32676 →   
 NA Connect →   
 ISO 2852 →

2




- Inspect: only use when clean and undamaged  
 - Inspectez: à n'utiliser que propre en bon état  
 - Prüfen: nur verwenden wenn unbeschädigt und sauber  
 - Kijk na: alleen schoon en onbeschadigd gebruiken  
 - Ispezionare: usare solo se pulito e non danneggiato  
 - Inspección: usar solo si está limpio y sin daño alguno

3



4



5




- Inspect: only use when clean and undamaged  
 - Inspectez: à n'utiliser que propre en bon état  
 - Prüfen: nur verwenden wenn unbeschädigt und sauber  
 - Kijk na: alleen schoon en onbeschadigd gebruiken  
 - Ispezionare: usare solo se pulito e non danneggiato  
 - Inspección: usar solo si está limpio y sin daño alguno

## REPLACE - REMPLACER - ERSETZEN - VERVANGEN - SOSTITUIRE - CAMBIAR

6



7



8

